

SITE INSPECTION REVIEW FORM

SITE NAME: Aetha Chemicals	
ALIASES:	
SITE I.D. #: ND 001471374	<u>·</u>
ITEM YES	ETE ? NO*
SITE LOCATION (INCLUDING MAP)	
SITE BACKGROUND	·
ENVIRONMENTAL SETTING (GEOLOGY, HYDROLOGY, METEOROLOGY, ECOLOGY + LAND USE)	
WASTE DESCRIPTION (PRESENCE + CONDITION OF WASTE + WASTE MANAGEMENT UNITS)	<u>-</u>
LABORATORY RESULTS (CORRELATED TO SAMPLE LOCATION MAP)	
HRS PRE - SCORE (PRELIMINARY + PROJECTED)	<u> </u>
POTENTIAL FOR DIRECT CONTACT	_
CONCLUSIONS + RECOMMENDATIONS	
REFERENCES	1
HRS PRE-SCORE: PRELIMINARY SCORE =	
PROJECTED SCORE =	

COMMENTS:		
HRS Scores ho	+ included in SI.	
	ells should be installed	100
Site, due to hog	h concentrations of con	taminants
defected in the soi	1 + groundwater &	
	0	
	•	
,		
		· · · · · · · · · · · · · · · · · · ·
		, •
· · · · · · · · · · · · · · · · · · ·		
•		•
EVIEWED BY:	TAG	F:

*IF ANY ITEM IS LACKING INFORMATION PLEASE DESCRIBE IN COMMENTS